

Table (i). Acoustic Assessment Summary Table – Steady Sources – Current, Post-Abatement

Point of Reception	Description of Reception Point	Site L _{eq} (dBA)			Verified by Acoustic Audit	Performance Limits (dBA)			Compliance with Performance Limit
		Day	Evening	Night		Day	Evening	Night	
1a	Residential Dwelling Outdoor POR	44	44	N/A	Yes	50	50	N/A	Yes
1b	Residential Dwelling 1st Storey Plane-of-Window POR	45	45	45	Yes	50	50	45	Yes
2a	Residential Dwelling Outdoor POR	44	44	N/A	Yes	50	50	N/A	Yes
2b	Residential Dwelling 1st Storey Plane-of-Window POR	45	45	45	Yes	50	50	45	Yes
3a	Residential Dwelling Outdoor POR	43	43	N/A	Yes	50	50	N/A	Yes
3b	Residential Dwelling 1st Storey Plane-of-Window POR	45	45	45	Yes	50	50	45	Yes
4a	Residential Dwelling Outdoor POR	42	42	N/A	Yes	50	50	N/A	Yes
4b	Residential Dwelling 1st Storey Plane-of-Window POR	44	44	44	Yes	50	50	45	Yes